

# 32 ft 1955 Custom Sedan Cruiser

**US\$39,900**

Anacortes, Washington, United States



## Boat Details

Make:	<b>Custom</b>	Class:	<b>Cruiser</b>
Model:	<b>Sedan Cruiser</b>	Hull Material:	<b>Wood</b>
Year:	<b>1955</b>	Beam:	<b>10 ft</b>
Length:	<b>32 ft</b>	Boat Location:	<b>Anacortes, Washington, United States</b>
Price:	<b>US\$39,900</b>	Heads:	<b>1</b>
Condition:	<b>Used</b>	Fuel Type:	<b>Diesel</b>



### Russ Meixner | West Yachts

West Yachts LLC, Anacortes, Washington, United States

Tel: **360-299-2526**

[russ@west-yachts.com](mailto:russ@west-yachts.com)

[www.yachtworld.com/westyachts](http://www.yachtworld.com/westyachts)

## Description

**PRICE REDUCTION!!!**

**By Appointment Only**

Custom Built in 1955 by shipwright Raigh Lowery, for himself to cruise the Inside Passage in retirement. This sedan cruiser was influenced by a 1930's Mathews design.

Great vessel to cruise the Puget Sound, San Juan Islands, Canadian Gulf Islands & Desolation Sound

## Information & Features

### Dimensions

LOA: **35 ft**

Beam: **10 ft**

### Accommodations

Heads: **1**

## 32' Custom Sedan Cruiser 1955

### SPECIFICATIONS:

- LOA - 35'
- LOD - 32'
- LWL - 32'
- Draft - 2' 10"
- Hull - Semi-Displacement

### CONSTRUCTION:

- Hull - Constructed of cedar on oak, red cedar below the waterline and yellow cedar above the waterline.
- Decks - Constructed of red cedar originally in canvas bedded in white lead and painted. Everything removed from decks including spray skirt/bulworks. All decks refastened, canvas replaced with 1/8" marine plywood bedded in thickened West epoxy, filled, faired and topcoat with 3-coats of west epoxy 2nd coat reinforced with fiberglass cloth matrix, 3rd coat (fill coat) sanded, painted and nonskid. **NEW 2006**
- House - Whole house was sanded to wood, sealed with epoxy, primed twice and 2-coats painted of Petit Marine Easyepoxy Paint. **NEW 2006**
- Cabin Sole - Sole floor boards replaced with 3/4" marine ply, encapsulated in epoxy, **NEW 2006** Original carpet glued on.
- Hull Transom - 16 frames were added port and starboard from the transom to the main bulkhead. Hot driver between existing frames to reinforce aft bilge turn, resulting in frames every five inches aft of the main bulkhead. This area was recalked with cotton and seams paved with tar, new frames were fastened with #12 1 3/4" hot dipped galvanized screws all butt blocks replaced. - **NEW 2019**

### TANKAGE:

- FUEL - 100 Gallons in 2 Tanks - Tanks Removed, Inspected,& Replaced - Painted with 2 Coats of Rust Inhibiting Paint - **NEW**
- DOMESTIC WATER - 40 Gallons in 2 Poly Tanks - **NEW 2017**
- HOT WATER TANK - 70 Gallons in 3 Tanks (40/15/15)
- WASTE -

### INTERIOR:

- Sleeps - 4
- Galley Counter Top & Backsplash - Stainless Steel
- Galley Sink - Stainless Steel
- Pressure Cold Water Pump
- Manual Cold Water Pump
- Refrigeration - 120Volt AC Refrigerator - Located in Cockpit
- Dinette - 2 Person
- Cabin Lights - LED Bulbs - **NEW**
- Stereo - Kenwood KDC-265U Pandora Heart iPod/USB Stereo
- Clock & Barometer

### MECHANICAL / ELECTRICAL:

- Single 1992 Yanmar 4LHDTE, Turbo-Charged 4-Cylinder, 170hp - **Installed 2016**
- Hours - 1,150
- Engine - **Serviced February 2022**
- Cruise - 1600 to 1700 rpms @ 8 to 10 Knots @ 1 to 2 gph
- Propeller Shaft - **NEW 2016**
- Propeller - **NEW 2016**
- Inverter - 3000 Watt Inverter
- Solar Panels - (2) 125Volt Panels installed
- Batteries - (4) 6Volt Golf Cart Wired to Produce Deep-Cycle 12Volt Power = 120Volt AC Power

#### **NAVIGATION / COMMUNICATION:**

- VHF - West Marine MC795
- GPS - GARMAN GPSmap 182C Color Map
- Compass - Saturn
- Fish Finder - Lowrance Elite-5, Color Display
- Autopilot - Bendix Automatic Pilot

#### **GROUND TACKLE:**

- Windlass - Simpson Lawrence Vertical Shaft Anchor Winch
- Chain - 3/8" BBB
- Gypsy - Installed - **NEW**

#### **SAFETY:**

- Navigation Lights
- Fire Suppression System - 1st Manual Engine Room System - Tank Located in Starboard Cockpit Locker.  
2nd Automatic System in Lazarrette for Battery Fire.

#### **MISCELLANEOUS:**

- Bottom Paint - Stripped to Wood - (1) Thin Coat of Bottom Paint - Then (20 Full Coats of Bottom Paint - **NEW February 2022**
- Zincs - **NEW February 2022**
- **Staging and Personal Items to be Removed at Time of Sale**























